Application/Control Number: 09/824,367 Page 2

Art Unit: 2451

Reason for Allowance

The following is an examiner's statement of reasons for allowance:

1. Applicant stated that "..multiplexing cycle can be considered equivalent to a time to leak 188-byte data" (see Page 3 of the Pre-Brief Conference Request filed in 4/15/08) and "the time

division multiplexing cycle is irrespective of the transport rate of said plurality of bit streams"

(see Page 4 of the Pre-Brief Conference Request filed in 4/15/08).

2. In light of applicant's statement made on 4/15/08 (see above), none of the prior art of

records teach or suggest in combination:

A data multiplexing method for a data multiplexer performing time division multiplexing of a

plurality of bit streams, said method comprising the steps of:

extracting access unit information necessary for multiplexing processing from each of said

plurality of bit streams; calculating a time division multiplexing cycle for each of said plurality

of bit streams, such that a separator separates multiplexed data by a specified method on the

basis of said information extracted by processing at said extracting step, wherein the calculating

step calculates the time division multiplexing cycle irrespective of the transport rate of said

plurality of bit streams, performing time division multiplexing of said plurality of bit streams on

the basis of a result calculated by processing at said calculating step; and a second calculating

step for calculating a data occupancy rate of a virtual data buffer of said separator, wherein said

multiplexing determines an order in which said plurality of bit streams are multiplexed on the

basis of the data occupancy rate of said virtual data buffer calculated by the second calculating

step.

Application/Control Number: 09/824,367 Page 3

Art Unit: 2451

Any inquiry concerning this communication or earlier communications from the

examiner should be directed to KAREN C. TANG whose telephone number is (571)272-3116.

The examiner can normally be reached on M-F 7 - 5.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's

supervisor, John Follansbee can be reached on (571)272-3964. The fax phone number for the

organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent

Application Information Retrieval (PAIR) system. Status information for published applications

may be obtained from either Private PAIR or Public PAIR. Status information for unpublished

applications is available through Private PAIR only. For more information about the PAIR

system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR

system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would

like assistance from a USPTO Customer Service Representative or access to the automated

information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/K. C. T./

Examiner, Art Unit 2451

/John Follansbee/ SPE 2451